



ASSEMBLY INSTRUCTIONS


for TORHT

hardware list


- | | | |
|---|---|-------|
| A |  | x8pcs |
| B |  | x4pcs |
| C |  | x1pcs |
| D |  | x2pcs |
| E |  | x2pcs |



parts list



step 1. A x8pcs




* Screw on first and tighten all the screws after step 2.

step 2. B x4pcs

E x2pcs

D x2pcs



* Tighten all the screws.