


ASSEMBLY INSTRUCTIONS


for ZCDS




hardware list

- A  X20 pcs
B  X1 pcs


parts list




step 1. A  X14 pcs



step 2. A  X6 pcs



step 3.



* Tighten all the screws.