






ASSEMBLY INSTRUCTIONS

for SCA CDS



hardware list

- A  L=30x8pcs
- B  L=25x6pcs
- C  x1pcs
- D  L=40x2pcs

parts list

